

Oil Field Environmental Incident Summary

Incident: 20161019164308

Date/Time of Notice: 10/19/2016 16:43

Responsible Party: Wisco

Well Operator: WISCO, INC.

Well Name: WISCO SWD #1

Field Name: ROUND PRAIRIE

Well File #: 90247

Date Incident: 10/19/2016

Time Incident: 12:00

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 104

Sec: 26

Qtr: NW NE

Location Description:

Submitted By: Donald Plew

Received By:

Contact Person: Donald Plew

15495 Highway 2

Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

3 Mile

Distance Nearest Water Well:

3 Mile

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine	20	Barrels	20	Barrels		
-------	----	---------	----	---------	--	--

Other

Description of Other Released Contaminant:

N/A

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None, contained within berm

Action Taken or Planned:

Operator noticed spill during his rounds at SWD. He immediately turned on sump pump to pump fluid back into tank. Operator then drained filter pod and replaced valve. Hydrovac was called to begin cleanup.

Wastes Disposal Location: Saltwater will be pumped pack into Saltwater disposal. impacted class 5 from berm will be taken to Wisco landfill.

Agencies Involved:**Updates**

Date: 10/19/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to equipment failure, was contained within the diking according to the report. NDIC retains oversight.